Version 6.0.14.0

Version	6.0.14.0
Release date	31/01-2024
Type	Major release

Enhancements & New Features

Component	Description
General	Added support for new Leak Detector asset type XL3000 Flex.
Machine Interface	All Leak Detector assets now have machine interface support.
Barcode scanner	Added new endpoint in public web api for scanning barcodes.
EST-200	EST-200 assets running in a Gateway service can now be controlled in PLIS Factory.
Database Updater	Added prevention of updating a database with an expired license.
Factory	Added support for setting up Leak Detector assets, profiles and recipes.
Factory	Added searchbar to Assembly instruction when editting components, and filters on the components in the tree view, for easier editing.
Factory	Recipes and profiles now supports viewing change history, and restoring previous versions.
Factory	Added the "Test status" view module for displaying information about the latest run test for an asset.
Factory	Added support for managing Users.
Factory	Added support for managing User Groups.
Factory	Can now see active inter-gateway connections in PLIS Factory asset cockpit.
Factory	Measurement units can now be configured in PLIS Factory. Personal measurements units can be configured on the personal settings page available through the username in the top-right corner. Global measurement units can be configured in system setup.
Gateway Service	Added support for running the following asset types in a Gateway service • CPTX based assets • Leak Detector assets • MPC based assets • MPC2 based assets • AutoPrint • Compensation Sensor • Reject Point • Omnia II 8206 • HypotULTRA • EST Basic/EST-100 • Generic Interface • Kobra-II • Kobra-III

Bugfixes

Component	Description
Factory	Fixed some cases of texts that would not be displayed in correct language after initial load.
Factory	Fixed issue where content text of the unsaved changes warning was missing.
Factory	Fixed issue where new assets could not be marked as final or repair assets before saving and reloading.
Factory	Fixed issue where an asset could be marked as final asset and repair asset simultaneously.
Factory	Fixed slow loading of models on model overview by adding load more option and filtering.
Factory	Fixed slow loading of recipes on recipe overview by adding load more option added and filtering.
Factory	Fixed issue where selected barcode scanners would reset when editing assets with different gateways.

Factory	Fixed missing indicator on operator codes edit where selecting links in a deeper hierarchy didn't show in the folder structure.
Factory	The note entered when manually passing or failing a test is now shown in the results view.
Factory	Results in PLIS Factory now shows the charge media used in the test.
Factory	Fixed recipes rerendering and blinking when using context menu on detail rows of the grid.
Factory	Added save confirmation to smart limits, to help prevent unintentional saves when spending time on setting up the perfect smart limits.
Factory	Fixed issue where stop reasons cumulative percentage would show wrongly, due to missing names of the stop reason displayed, instead now shows a name "N/A(x)" to display correctly.
Factory	Fixed issues with creating overlapping recurring shifts and the initial start-end time when creating from context menu on unselected cells of the calendar.
HypotULTRA	Fixed issue where latest result was saved again when starting gateway.
Leak Detector	Fixed issue where using setting "abort test on device error" would abort test after scanning a new barcode.
Leak Detector	Fixed that auto gas was not supported.
MPC2	The input controls in the System Client section of the Gateway have been reordered so they are displayed properly.
Operator Interface Operator Terminal	Fixed issue with duplicated components when removing and adding components in multiple separate tests.
Operator Terminal	Removed two barcode scan output events that could not happen.
Operator Terminal	Fixed issue where incomplete assemblies allowed continue of test with a passed result.
Operator Terminal	Fixed the issue where the result of an text module would show the HTML markup used to set up the text.
Operator Terminal	Fixed issue where the option to add a repair note would not always be available.
Operator Terminal	Fixed issue where adding a failcode through OT hotspot module would show two results to repair for a single failcode.
Operator Terminal	Fixed inconsistent status when mounting components.
Operator Terminal	Fixed issue with PDF's with large filename saving but not loading correctly.
Operator Terminal	Fixed issues on Repair code module in operator terminal where the collection ID would show when the collection was no longer valid.
Master Service	Fixed issue where creating a new masterservice from PLIS Manager or PLIS Installer would set wrong language.
Master Service Gateway Service Factory	Fixed issue where creating a new asset and assigning it to a gateway, which runs as a service, would not start the asset automatically.
PLIS Manager Factory	Filtering on components when searching for results will now only include components that are actually mounted on the product.
PLIS Manager	Fixed ambiguous naming of a setting on EST900 & KT1886, that could be misinterpreted as disabled when enabled.