Version 6.0.14.2

Version	6.0.14.2
Release date	23/02-2024
Type	Minor release

Enhancements & New Features

Component	Description
PLIS Gateway	PLIS Factory can now connect to, and show status for, assets running in PLIS Gateway desktop application. This may require port 2752 to be opened in the firewall on the desktop PC, depending on firewall and network configuration.
Operator Interface	Added option to disable removal of previous repairs for Repair Interface

Bugfixes

Component	Description
Database	Improved deadlock and transaction handling of database queries.
MPC 2	Fixed that retry results were not saved.
CPT-X	Fixed that an added sensor would not be shown in the expected location.
CPT-X	Fixed that order was sometimes shown wrong.
Manager + Factory	Fixed issue in Manager and Factory where models would show multiple times under a recipe if they were using nested events.
Factory	Fixed issue where setting allow empty input on the number module in a OT recipe didnt reapply when later editing the recipe.
Calibration	Fixed error in sample grid when sample deviation is missing.
Calibration	Fixed that wrong template name was shown for some results.